DB 12/2/8

Cow Tag	9	Function Co	de P	8_5	
Brief Description: [timber element, p/s, condition, fragments]					
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos					
Also on inboard wil	bood,				
Types 1, 2, 5, 8					
No Fish symbol	Need wood fait	Centre la	Van all	. 16.	
No Fish Symbol, Need wood fast. centre layer, add.na. I change layer colo Wood Science: [rings, ARW, knots, sapwood, conversion]					
Now Sort Chow	Rodial at at	t scort clyoH			
Recommended action: [problems]	samples, additiona	l photos, mo	ulding, q	ueries and	15
	D. D TN	IT 27 10 3	No.	*	
Cleaned:	Recorded: The	17 27.10.2	Photos:		72
Oldanida.	HPM 20.1	- Contraction of the Contraction			
Checked: [corrections needed]			Initials 8	Date:	
Corrections Done [desktop, Faro Arm?]:			Initials 8	Date:	

