




DB 7/2/18

Cow Tag 104	Function Code S 11.7	
Brief Description: [timber element, p/s, condition, fragments] complete plank. CONCRECTIONS IN MARK, V. TARY woods		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos inboard:- POSSIBLE LINE FOR OFF and Greenrot from far end outboard:- TWO CLAMP MARKS:- NEXT TO END T.N FROM ART SCAPES outboard:- M.N.P inboard:- small hole on the land (drawn as limits) = animal bore hole the hole is located on the edge of the plank which is not shown in the drawing. It is not clear if this could be a compression mark, but not shown as it is not shown. 3 treatments just dip upper edge, off.		
Wood Science: [rings, ARW, knots, sapwood, conversion] C100H + S ARW: 180 mm. R.A.H beyond upper edge Radial		
Recommended action: [samples, additional photos, moulding, queries and problems] Check treatments		
Cleaned: 17/07/06 SS VT	Recorded: 19/07/06 DV	Photos:
Checked: [corrections needed] ✓		Initials & Date: NN 26/7/06
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

104 S11_7 Yardeni Vorst 19 July 2006



*3 remains left side
from bank level.*

COWTAG
104