DB 19/2/8 Cow Tag **Function Code** 520.1 57 Brief Description: [timber element, p/s, condition, fragments] and sown off Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN/RECORDING ufos Inboard. 2, added holes on aft end. Inscribed lines by middle Octboard: Wood surface detensisted. No wholle features Inboard: - 2 climp marks between 2nd & 3rd keenail + a possible clamp marks next to 5th Leenail: Also 2 square holes next 5th Leenail - rectengular hole on land between 5th + 6th treenail - aft end: 3 additional nails I imagens scabed his - Type I's on intoad netudio, very faint Wor the 18 aft scarf face. Stap 22rod Goo Wood Science: [rings, ARW, knots, sapwood, conversion] Lango to the beyond upper edo CTIOH. Recommended action: [samples, additional photos, moulding, queries and problems] Cleaned: M Recorded: Photos: pv 10/8/2006 Checked: [corrections needed] Initials & Date: NN 11 8 Initials & Date: Corrections Done [desktop, Faro Arm?]:

