


DB 19/2/8

|   |             |  |          |
|---|-------------|--|----------|
| Cow Tag   | 262         | Function Code  | S 22.1   |
| Brief Description: [timber element, p/s, condition, fragments]<br>Short fragment of lower edge  |             |  |          |
| Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos<br>1.B - N.N.F.<br>0.B - N.N.F. |             |  |          |
| Wood Science: [rings, ARW, knots, sapwood, conversion]  |             |  |          |
| Recommended action: [samples, additional photos, moulding, queries and problems]  |             |  |          |
| Cleaned:  | 24/08/06 BS | Recorded:  | 8/9/6 BS |
| Checked: [corrections needed]   | ✓           | Initials & Date:   | NN 8/9/6 |
| Corrections Done [desktop, Faro Arm?]:  |             | Initials & Date:   |          |