



DB 12/3/8

Cow Tag <u>527</u>		Function Code <u>56.2</u>
Brief Description: [timber element, p/s, condition, fragments] <u>Plant, good condition</u>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>inboard: 2 pegs in center nail holes</u> <u>Possible toolmarks off end.</u> <u>Type 3 inboard (&lt;) + (X) possibly OB</u> <u>Outboard: possible miscribbled lines (cross) off end.</u> <u>ARW marks on off end.</u> <u>Outboard off end possibly aborted beginning of cutting scarf - scribed line + axe cut(s).</u>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <u>cS 2 Hat off scarf. Pith beyond upper edge. Radial off scarf. Grain curving away at both ends. ARW = 195/52.</u>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: <u>MS/LB/VT</u> <u>22/05/06</u>	Recorded: <u>VT 01/06/06</u>	Photos:
Checked: [corrections needed] <u>✓</u>	Initials & Date: <u>NN 21/6/6</u>	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	

Being cleared  
by VT  
31/05/06



James' sketch



527 sq. 2 Vassilis Tsakiris 01 June 2006

