

DB 13/3/8

Cow Tag 560	Function Code S11.3A
----------------	-------------------------

Brief Description: [timber element, p/s, condition, fragments]

PART OF UPPER EDGE S11.3  
CRACK + BENDY


Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

NNF  
OB = hard not easy to ~~see~~ see for recording -

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]

sapwood  
fuzzy



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 26/09/06 US	Recorded: UT 27/09/06	Photos:
Checked: [corrections needed] /	Initials & Date: NN 18/10/06	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	