

DB 15/3/8

Cow Tag **576**


Function Code **P9-8A**

Brief Description: [timber element, p/s, condition, fragments]

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:

Recorded:

Photos:

01.06.05 TNJ

Checked: [corrections needed]

Initials & Date:

18/04/07 SJ VT

Corrections Done [desktop, Faro Arm?]:

Initials & Date: