


DB 27/02/08

Cow Tag <b>605</b>		Function Code <b>P10-<del>1B</del>2B</b>
Brief Description: [timber element, p/s, condition, fragments] <p>Forward scarf damaged/missing</p>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <p>Type 1 Inscribed Lines</p>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <p>Radial. Pith beyond upper edge c 90H + 10S. ARW = 192</p>		
Recommended action: [samples, additional photos, moulding, queries and problems] <p>DEND - Parent of dend sample 2324</p> <p>ReRecorded: TNJ 01/12/2006</p>		
Cleaned:	Recorded: <b>HPM 23.03.05</b>	Photos:
Checked: [corrections needed]		Initials & Date: <b>NN 30/1/7</b>
Corrections Done [desktop, Faro Arm?]:		Initials & Date: