


DB 09/12/09

Cow Tag 608		Function Code P4.1
Brief Description: [timber element, p/s, condition, fragments] SMALL FRAGMENT OF P4.1, BOW END		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: 12/04/06 BS	Recorded:	Photos: 75
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: