

1ank 18

Cow Tag	640	Function Code	F16-2
---------	-----	---------------	-------

Brief Description: [timber element, p/s, condition, fragments]

Fragmented
Recordable?


DB 07/12/09

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

*Not recordable, bad condition.
Original surfaces consists of treated lds.
Do not record.*

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:	Recorded:	Photos:
05/12/06 PJ		

Checked: [corrections needed]	Initials & Date:

Corrections Done [desktop, Faro Arm?]:	Initials & Date: