

Cow Tag

076

Function Code


S2#7

Brief Description: [timber element, p/s, condition, fragments]

Fragment - for Scry

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING


Oblique oak works O.B  
Lp.: No JAM/STOP CORNERS



OB 03/12/09

T.1	T.2	T.3	T.4	T.5	T.6	T.7	

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 21/09/08 <sup>USJ</sup>	Recorded: 05/11/07 BJ	Photos:
-------------------------------------	--------------------------	---------

Checked: [corrections needed]	Initials & Date:
-------------------------------	------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
--	------------------