

DB 6/2/18


Cow Tag *OP2* Function Code *S17-3*

Brief Description: [timber element, p/s, condition, fragments]
fragment

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING
possible old marks on DB face - no stop marks

| | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|
| T.1 | T.2 | T.3 | T.4 | T.5 | T.6 | T.7 | T.8 |
| | | | | | | | |

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: *21/04/08* *JS* Recorded: *24/01/07* *MS* Photos:

Checked: [corrections needed] Initials & Date: *18/04/07* *JS* *VT*

Corrections Done [desktop, Faro Arm?]: Initials & Date: