

96/1

FILE NOTE - NETTLEHAM

MAP SQUARE SK 97 SE NGR SK 99567478
Centre point.

RE: WATCHING BRIEF ON LCC GRANT AIDED POND CONSTRUCTION -
NETTLEHAM LODGE - THURSDAY 11 JANUARY 1996

Watching Brief carried out on the above works by Stephen Catney.

The whole area had been disturbed during the A46 Bypass construction and was pock marked with holes filled with debris from the construction process.

The whole area had also been covered with a layer of clay up to 30cm thick which again has re-deposited material from the construction of the road. Approximately 1/3rd of the pond area was cut into the natural slope while around 2/3rds of the pond was built up. The area cut into the natural slope was carefully top soiled using a JCB with a non-toothed bucket and no archaeological features were identified. In addition not a single archaeological find was identified.



Lincolnshire

Mrs Achille
Nettleham Lodge

Pond Construction Site Plan

Scale 1:1,250



Copyright Licence No: AL50095A

Irregular, landscaped
spoil disposal and
retention bank.

Possible Wild
Flowers On Spoil

Avoid
damage to
underlying pipeline

Graded edge
for
safety

B M 31.22m

Marshy Area

GRIMSBY

A46

The
Lodge

