3197 Ground floor - detail view of ground floor chimney breast and blocked up fire opening.

3198 Ground floor - looking west from position of 3197. The staircase is to the right and the opening through the main north / south cross wall leads into an oil storage tank area.

3199 Ground floor - looking west through the access into the oil storage area referred to in 3198.

3200 Ground floor - looking west - internal view of tank room with rear wall being the wall into the adjacent yard - refer to photograph 3234.

3201 Ground floor - looking west - vertically rotated view to 3200. Note: The step up. It is likely that this part of brickwork was an infill to a previous opening (note: the timber lintel visible on 3200 and 3234).

3206 Front elevation - upper floor junction of Seddon Building with 211 Westgate Road.

3207 Front elevation - vertically rotated view of 3206 showing the northern jamb of the loading doors.

3208 Front elevation - detail of loading door head.

3209 Front elevation - vertically rotated view of 3208 showing render finish to jambs and thin concrete thresh.

3210 Front elevation - detail of first floor north window.

3211 Front elevation - vertically rotated view of above.

3212 Front elevation - looking south west showing junction of Seddon Building with Swinburne Place.

3213 Front elevation - looking west at same junction as 3212. Note: the vertical junction sits south of the gable above.

3214 Front elevation - low level view of above showing a blocked up opening to a basement level.

3215 Front elevation - ground floor window.

3216 Front elevation - first floor window.

3217 Front elevation - second floor window.

3218 Contextual photograph - looking North West towards Westgate Road.

3219 Front elevation - detail of step up to front door.

3220 Contextual photograph - looking south west towards Swinburne Place.