

DB 21/2/18

Cow Tag	175	Function Code	P9_6
---------	-----	---------------	------

Brief Description: [timber element, p/s, condition, fragments]

~~Thin~~ Thick Plank, good condition

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos


Treenail is missing @ Frame station 36

Type 2, Type 1 or 6?

~~Need wood fasteners centre layer added~~

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial, c100H+5S  
Pith beyond lower edge



Recommended action: [samples, additional photos, moulding, queries and problems]

Photos of intentional marks

ReRecorded TNJ 09/11/2006

Cleaned:	Recorded: HPM 23/02/05	Photos: <del>Additional</del> Intentional Marks? 28/01/08
Checked: [corrections needed]		Initials & Date: NN 30/1/7.
Corrections Done [desktop, Faro Arm?]:		Initials & Date: