

DB 12/2/18

Cow Tag 194	Function Code P12.6
Brief Description: [timber element, p/s, condition, fragments] Good condition, quite knotty	
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>Inboard</u> Inscribed line for of aft scarf, axe marks on left scarf ^{aft scarf} axe marks on adjacent adjacent to 3rd tree nail from aft end, possible axe mark for of 6th tree nail/tree nail pair from for end. Inscribed line for of 4th tree nail from for end. Inscribed line under cow tag. <u>Outboard</u> wedge in 3rd tree nail from aft end	
Wood Science: [rings, ARW, knots, sapwood, conversion] C90N + 5S at aft scarf. ARW = 195/95. Radial. Pith beyond upper edge. A generally knotty timber with numerous tears as a result.	
Recommended action: [samples, additional photos, moulding, queries and problems] 2 additional nails outboard scarf forward face have nail angle less <u>Not</u> measured with 15 cm rod. (also other additional nail with angle far less than 15cm)	
Cleaned: KHM, BJ 15/06/06	Recorded: DV. 21/06/2006.
Checked: [corrections needed] ✓	Photos: Initials & Date: NV 21/6/6
Corrections Done [desktop, Faro Arm?]:	Initials & Date: