

DB 26/2/8

Cow Tag 319	Function Code 522.4	
Brief Description: [timber element, p/s, condition, fragments] Complete stall		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos ool board:- possible (ins) between 2nd/3rd T.N from for end T.N (5cm from aft) has wedge Star impressions on 2 nailheads INBates:- inscribed lines → Type ① ✓ → Type ③ ✓ 4 POSSIBLE CLAMP MARKS Marks inscribed lines at step in land for scarf on 821.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial, c 70H + 5S ARW = 280/75 Pith beyond lower edge		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: BF, VT 18/08/06	Recorded: AK 22/8/06	Photos:
Checked: [corrections needed] ✓		Initials & Date: MN 22/8/06
Corrections Done [desktop, Faro Arm?]:		Initials & Date: