


OB 26/2/8

Cow Tag	322	Function Code	S 12.4A
Brief Description: [timber element, p/s, condition, fragments] SHORT FRAGMENT OF S 12.4 - forward scarf. pile damaged at off end			
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos			
Wood Science: [rings, ARW, knots, sapwood, conversion] Killed ~80A. Pith uncertain ARW = 230/20			
			
Recommended action: [samples, additional photos, moulding, queries and problems]			
Cleaned:	Recorded:	Photos:	
01/08/06 BJ	01/08 UB REC. RJB 10/2007		
Checked: [corrections needed] ✓		Initials & Date: NM 10/8/6	
Corrections Done [desktop, Faro Arm?]:		Initials & Date:	