

DB 26/2/8  
529-3

Cow Tag

333

Function Code

Brief Description: [timber element, p/s, condition, fragments]

Complete plank

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

0.3 - N.P.F

1.3 - T.1 nail for of aft scarp  
ross T.2 below 1st T.N for of aft scarp

T.6 above steps on land

T.6 a 50 cm for of step on land

T.1

T.2

T.3

T.4

T.5


T.6

T.7

T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial ~ 100H P.H. beyond  
upper edge on growth track



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:

LB 35  
15/09/08

Recorded:

Photos:


Checked: [corrections needed]

Initials & Date:


NN 10/10/08

Corrections Done [desktop, Faro Arm?]:

Initials & Date:



333 929\_3 Toby N. Jones 17 September 2006



75

76