

DB29/2/08

Cow Tag 342	Function Code S31.325
----------------	--------------------------

Brief Description: [timber element, p/s, condition, fragments]
AFT END OF PLANK

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING


LARGE CRACK OB, PREV. COVERED BY TINGLE 344
DOUBLE TREENAILS; ALSO SOME TREENAILS LARGER THAN NORMAL? VAGUE TYPE 3
ALSO VERTICAL LINES INSCRIBED AT END OF CRACKS
1/2 soft surface + remnants of unscribed line
Type 1 next to middle treenail

- didn't see any ins. lines during recording - MS.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
✓		✓					

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radius ~ 100H. ARW = 2.15mm
P.H. beyond upper edge.




Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 19/09/06 LB	Recorded: MS 22/9/6	Photos:
-------------------------	------------------------	---------

Checked: [corrections needed] ✓	Initials & Date: NN 9/10/6
------------------------------------	-------------------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
--	------------------

342 S31_2B Matt Simmonds 21 September 2006



cut in anticipation