


DB 11/3/8

Cow Tag 358	Function Code S 18.2 B	
Brief Description: [timber element, p/s, condition, fragments] fragments of plank - one of scarf		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos I.B - N.M.P. O.B - N.M.P. - Sapwood? - animal bore hole I.B.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Near radial c 95 H. PTH beyond upper edge. Possibly some sapwood on lower edge. ARW = 212/95.		
Recommended action: [samples, additional photos, moulding, queries and problems] Check out (x-sects) re aboard + DB layering		
Cleaned: 25/09/06	Recorded: 6/09/2006 DV.	Photos:
Checked: [corrections needed] ✓	Initials & Date: MN 18/10/6	
Corrections Done [desktop, Faro Arm?]: ✓	Initials & Date: MN 18/10/6	