

DB 11/3/8

Cow Tag	368	Function Code	frag of 2333
---------	-----	---------------	--------------

Brief Description: [timber element, p/s, condition, fragments]

Small fragment


Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

M.P.F.

I identified/recorded this as Forward scarf with cow tag on 1st board side. ~~there was a~~ Assuming I could trace a row impression on the cow tag side and that the bend on the lower side is not visible.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
(?)							

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:	Recorded:	Photos:
15/09/06 BJ	15/12/06 VT	

Checked: [corrections needed]	Initials & Date:
	18/04/07 BJ VT

Corrections Done [desktop, Faro Arm?]:	Initials & Date: