DB 091	12/09		Fr	aming Fr	na? 117	
Cow Tag 436		Function	Code	Timber	497 1	
Brief Description: [timber element, p/s, condition, fragments]						
Probable Frame Fry of back marks						
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING  two pertial treenails, one Fe spike  Not to Fero						
two partial	treens.	ls, one	Fe s	oike	4	
Not to Fare					,	
T.1 T.2 T.3	T.4	T.5	T.6	T.7	T.8	
Wood Science: [rings, ARW, knd	ots, sapwood, co	onversion]				
Fast Grown oak						
Recommended action: [samples, additional photos, moulding, queries and problems]						
Cleaned:	Recorded:		Photos:	10/01 21 Photo	108R.	
Checked: [corrections needed]			Initials 8	Initials & Date:		
Corrections Done [desktop, Faro Arm?]:			Initials 8	Initials & Date:		