


DB 5/3/2008

Cow Tag 466		Function Code 5 14- 3 3	
Brief Description: [timber element, p/s, condition, fragments] SOLID PLANK, SEVERELY MARKED. Near complete.			
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos			
<p>IN BOARDS:- DEEP IMPRESSION OTV LINES 15 cm AFF OF COW TAG - Yes but forward of center.</p> <p>SEMI CIRCULAR IMPRESSION LINE FROM 60 cm FROM AFF TO 1 m FROM OF AFF LINE 20 cm FROM OF COW TAG LINE 2 m AFF OF FROM END</p> <p>OUTBOARDS:- POSSIBLE INSCRIBED LINES TOWARDS THE AFF END OF TIMBER</p> <p>STRANGE MOULDINGS C. L. 6 m FROM AFF END OF PLANK - PRES POST DEP - NIGEL</p> <p>- Inboard: limits with lots of snits over it over the width of the plank are compressed areas</p> <p>- Inboard: two small elongated additional (nails) holes on & just under the land one near aft end, one near forward end. (drawn as limits, but put an angle on it)</p>			
Wood Science: [rings, ARW, knots, sapwood, conversion]			
<p>Radial, p/s beyond lower edge 90W45S. ARW = 24S/AS. Numerous epicormic? branches.</p>			
Recommended action: [samples, additional photos, moulding, queries and problems]			
<p>→ Check on coding for SH4.</p>			
Cleaned: KM BJ 20/06/06 LB MJ VT	Recorded: 13/07/06 DV	Photos:	
Checked: [corrections needed] ✓		Initials & Date: NN 26/7/6.	
Corrections Done [desktop, Faro Arm?]:		Initials & Date:	

- Inboard: two possible clamp marks
- NB forward end of plank does have normal end, therefore no ring of 90W45S!
Wrong!