





12/3/8

Cow Tag <b>479</b>	Function Code <b>S12.5</b>	
Brief Description: [timber element, p/s, condition, fragments] <b>Good condition wood, A NUMBER OF CRACKS</b>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <b>INBOARDS:- INSCRIBED LINES 'N' C. 30 cm AFT OF COW TAG</b> <b>INSCRIBED LINE 60 cm FROM COW TAG</b> <b>- marking edge of frame?</b> <b>OUTBOARDS:- INSCRIBED LINES C. 1m FROM FOR EDGE</b> <b>- TYPE 1) ALSO 6 VERTICAL LINES</b> <b>Numerous wooden nails + cracks-</b>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <b>80% ARW = 280/80</b> <b>Radial. Pit beyond upper edge on growth trail. Some wavy grain.</b>		
Recommended action: [samples, additional photos, moulding, queries and problems] <b>PHOTO GRAPHS TAKEN OF INBOARDS FOR SCAR - LOTS OF CRACKING FROM INBOARDS TIMBER</b>		
Cleaned: <b>MS 3J</b> <b>de/06/06 KHM VT</b>	Recorded: <b>23-6-06</b> <b>DV.</b>	Photos:
Checked: [corrections needed] <b>NN</b>	Initials & Date: <b>27/6/6</b>	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	



1/17/08  
Type 2



479 S12.5 Yards/Vest 23 June 2008

1/17/08  
Type 2