




DB 5/3/2008

Cow Tag 460	Function Code S 12.6	
Brief Description: [timber element, p/s, condition, fragments] Good condition, tangle on fore end.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos Outboard: Large abundance of sawnails Wooden pegs in cluster and holes. Inscribed lines (type 3) on fore scarf. Inboard: <u>type 1</u> inscribed lines on aft end Tool marks same side.) 2 or 3 sets Possible damp mark inboard near aft end.		
Wood Science: [rings, ARW, knots, sapwood, conversion] Numerous trees. Growth trend suggests path beyond lower edge c/100 A ARW = $210/100 = 2.1\text{mm}$ Radial 		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: MS/VT 28/06/06	Recorded: 30/06/2006 MNR	Photos:
Checked: [corrections needed] ✓		Initials & Date: MN 11/7/6.
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



← TINGLE

modem.

480 S12, 8 Moritka Malaysia-Riuhle 30 June 2008