



DB 5/3/2008

Cow Tag 483		Function Code S12.9
Brief Description: [timber element, p/s, condition, fragments] TRUNCATED PLANK, GOOD CONDITION		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD:- UNUSUAL STRAIGHT LINES AT AFT END (TYPE 2?) OUTBOARD:- DIMPLES ON SOME TREENAILS TOOLMARKS ON SCARP & UPPER EDGE UNUSUAL MARKS AROUND 3. TREENAIL AFT OF FORW. END. RECORDED AS AXE MARKS - NOT SURE THOUGH		
Wood Science: [rings, ARW, knots, sapwood, conversion] c85 H Radial. Pith beyond lower edge. ARW = 195/85		
Recommended action: [samples, additional photos, moulding, queries and problems] - THE ABOVE MENTIONED TREENAIL - HOLE HAS A VERY NICELY BEVELLED EDGE - change centre on wrong layer.		
Cleaned: 33 11/07/06 VT	Recorded: 13.07.06 AK	Photos:
Checked: [corrections needed] ✓	Initials & Date: NN 27/7/6	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	

check in corner panel



483 S12_9 Angola Karsten 13 July 2006

