

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 1 - Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Phase 1: Condition survey and conservation treatment vol 1	Lever Arch file – Text and Figs	Box 1
Phase 1: Condition survey and conservation treatment vol 2	Lever Arch file – Colour Plates	Box 1
Phase 1: Condition survey and conservation treatment vol 3	Lever Arch file – Transparencies	Box 1
Phase 2: Condition survey and conservation treatment vol 1	Lever Arch file – Text and Figs	Box 1
Phase 2: Condition survey and conservation treatment vol 2	Lever Arch file – Colour Plates	Box 1
Phase 2: Condition survey and conservation treatment vol 3	Lever Arch file – Transparencies	Box 1
Record of treatment and additional investigation of the Nave Ceiling following a fire in the Cathedral on 22nd November 2002	Lever Arch file – Text, Figs, Plates and Transparencies	Box 1

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 2 – Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Phase 3: Condition survey and conservation treatment vol 1	Lever Arch file – Text and Figs	Box 2
Phase 3: Condition survey and conservation treatment vol 2	Lever Arch file – Colour Plates	Box 2
Phase 3: Condition survey and conservation treatment vol 3	Lever Arch file – Transparencies	Box 2
Phase 4: Condition survey and conservation treatment vol 1	Lever Arch file – Text and Figs	Box 2
Phase 4: Condition survey and conservation treatment vol 2	Lever Arch file – Colour Plates	Box 2

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 3 – Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Phase 4: Condition survey and conservation treatment vol 3	Lever Arch file – Transparencies	Box 3
Phase 5: Condition survey and conservation treatment vol 1	Lever Arch file – Text and Figs	Box 3
Phase 5: Condition survey and conservation treatment vol 2	Lever Arch file – Colour Plates	Box 3
Phase 5: Condition survey and conservation treatment vol 3	Lever Arch file – Transparencies	Box 3
Record of treatment and additional investigation of the Transept ceilings following a fire in the Cathedral on 22nd November 2002	Lever Arch file – Text, Figs, Plates and Transparencies	Box 3
Condition survey and Emergency Conservation Treatment: The Nave Ceiling, St Peter, St Paul and Psaltery Player Lozenges	Lever Arch file – Text, Figs, Plates and Transparencies	Box 3

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 4 – Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Reports I: Published and unpublished papers; also some 1995-6 letters	Box File – Papers	Box 4
Reports II: Mainly conservation reports; also some letters	Box File - Papers	Box 4
Final Report I: Early draft text plus emails and letters 2009-15	Box File - Papers	Box 4
Final Report II: Early draft text plus letters and emails 2004-8	Box File –Papers	Box 4

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 5 – Contents

Brief description of Contents	Physical Description	Location
1994-6: letters and papers	Box File I – Papers	Box 5
1997: letters and papers	Box File II – Papers	Box 5
1997-8: letters and papers	Box File III – Papers	Box 5
1998-9: letters and papers	Box File IV - Papers	Box 5

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 6 – Contents

Brief description of Contents	Physical Description	Location
Phase 2: 1999-2000: letters and papers	Box File V:	Box 6
Compotec: papers relating to EU Compotec grant	Box File – Papers	Box 6
Zillis: notes and photographs	Lever Arch File – Papers, Prints	Box 6
Phase 1: notes, minutes, reports	Lever Arch File – Papers	Box 6

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 7 – Contents

Brief description of Contents	Physical Description	Location
Phase 2: notes, minutes, reports	Lever Arch File – Papers	Box 7
Phase 3: notes, minutes, reports	Lever Arch File – Papers	Box 7
Phase 4: notes, minutes, reports	Lever Arch File – Papers	Box 7
Phase 5: notes, minutes, reports	Lever Arch File – Papers	Box 7

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 8 – Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Phase 3: 2000-1, letters and papers	Box File VI – Papers	Box 8
Phase 4: 2001-2, letters and papers	Box File VII – Papers	Box 8
Phase 5: 2001-4, letters and papers	Box File VIII – Papers	Box 8

## PETERBOROUGH CATHEDRAL NAVE CEILING AND RELATED STRUCTURE ARCHIVE

### BOX 9 – Contents

<b>Brief description of Contents</b>	<b>Physical Description</b>	<b>Location</b>
Displays an Signage	Red card file	Box 9
European Grant Application	Red card file	Box 9
Hildersheim Zillis and Dadesjo	Red card file	Box 9
Seminar 1998	Red card file	Box 9
Computec Seminar 2001	Red card file	Box 9
Team Meeting Minutes	Red card file	Box 9
Tender documents	Red card file	Box 9
Tender documents (copies)	Buff transfer case	Box 9
Quotes and invoices	Red card file	Box 9
Video	Red card file	Box 9