

FYFIELD MANOR.



Fig. 1.

Taunt, Oxford.

BEFORE RESTORATION.

FYFIELD MANOR.



Taunt, Oxford.

Fig. 2.

AFTER RESTORATION.

FYFIELD CHURCH.




Fig. 3. BEFORE THE FIRE.

Taunt, Oxford.

FROM THE NORTH.

FYFIELD CHURCH.



Fig. 4. BEFORE THE FIRE.

FROM THE SOUTH.

FYFIELD CHURCH.



Fig. 5. BEFORE THE FIRE.

Taunt, Oxford.

INTERIOR LOOKING EAST.

FYFIELD CHURCH.




Fig. 6. OCTOBER 27th, 1893.

Taunt, Oxford.

FROM THE SOUTH.

FYFIELD CHURCH



H.W.T.

Fig. 7. OCTOBER 27th, 1893.

Taunt, Oxford.

SOUTH CHAPEL AND CHANCEL.

FYFIELD CHURCH



H.W.T.

Fig 8. OCTOBER 27th, 1893.

Taunt, Oxford.

INTERIOR LOOKING EAST.

FYFIELD CHURCH.



Fig. 9. OCTOBER 27th, 1893.

Taunt, Oxford.
INTERIOR LOOKING WEST.

FYFIELD CHURCH.




Fig. 10. OCTOBER, 27th, 1893.

Taunt, Oxford.

INTERIOR OF NORTH AISLE.

FYFIELD CHURCH.



Taunt, Oxford.

FROM THE SOUTH.

Fig. 11. 1917.

FYFIELD CHURCH.



Walton Adams & Sons Reading

Fig. 12. 1917. WEST DOORWAY AND INTERIOR LOOKING EAST.

FYFIELD CHURCH.



Watton Adams & Sons, Reading

Fig. 13. 1917.

NORTH DOORWAY.

FYFIELD CHURCH.



Walton Adams & Sons, Reading

Fig. 14. 1917.

FROM THE EAST.

FYFIELD CHURCH



Fig. 15. 1917.

Walton Adams & Sons, Heading

SOUTH SIDE OF CHANCEL.

FYFIELD CHURCH.



Fig. 16. 1917.

Taunt, Oxford.

INTERIOR LOOKING EAST.