



Overall site plan of the wreck remains as recorded across six seasons of survey, 2004-2010.




*Detail of the western
section of wooden
hull remains.*



Results of timber sampling for wood identification on the western section of the wreck.

Detail of the eastern section of wooden hull remains.



Results of timber sampling for wood identification on the eastern section of the wreck.

