# A Watching Brief on Demolition Works at The Garage, The Mines, Benthall, Shropshire

by H R Hannaford

# **Archaeology Service**



Archaeology Service Report Number 310 © Shropshire Council February 2012

# A WATCHING BRIEF ON DEMOLITION WORKS AT THE GARAGE, THE MINES, BENTHALL, SHROPSHIRE

by H R HANNAFORD MIfA

A report for Artemis Developers Ltd.





#### **CONTENTS**

		Page No
SUMMARY		1
1	INTRODUCTION	2
2	ARCHAEOLOGICAL AND HISTORICAL BACKGROUND	2
3	THE WATCHING BRIEF	2
4	REFERENCES	3

#### **ILLUSTRATIONS**

- Figure 1: The location of the study area
- Photo 1: The south end of the street frontage buildings, looking southwest
- Photo 2: The east range of buildings on the street frontage, looking northwest
- Photo 3: The site, looking south
- Photo 4: Doorway on the street frontage, with stone work to either side; (scales 2m and 1m)
- Photo 5: The rear of the buildings on the street frontage, looking northeast
- Photo 6: Demolition work in progress, looking southeast

## SUMMARY

In December 2011 demolition work was carried at The Garage, The Mines, Benthall, Shropshire, in order to prepare the site for redevelopment. The site lies in an area formerly occupied by a clay tobacco pipe factory, which started in the 18th century and continued production until 1900. It was a condition of the planning consent that the demolition of the existing structures on site be accompanied by an archaeological watching brief.

#### 1 INTRODUCTION

- **1.1** Benthall is situated in east Shropshire on the south side of the Ironbridge Gorge, some 20km southeast of Shrewsbury town centre and 6km south of Telford town centre. There is a proposal to demolish the existing buildings and factory unit and level the site at The Garage, The Mines, Benthall, Shropshire (NGR SJ 6698 0264).
- **1.2** The development site lies in an area formerly occupied by a clay tobacco pipe factory, which started in the 18th century and continued production until 1900. In 1885 it was said to be one of the largest factories of its kind in England (Historic Environment Record [HER] No. 03984 "Clay pipe works c 510m SE of Broadacres Farm"). It was considered possible therefore that archaeological remains relating to this former industry might survive within the study area.
- **1.3** Because of the potential significance of the archaeological resource it was considered necessary that any groundworks associated with the demolition be accompanied by the implementation of a programme of archaeological work.
- **1.4** The aim of the programme of archaeological work was to allow for the preservation by record of any archaeological remains that were encountered during the works.
- **1.5** The Archaeology Service, Shropshire Council, was commissioned by Artemis Developers Ltd. to carry out the archaeological watching brief on the demolition work in accordance with a written scheme of investigation (WSI) approved by the Historic Environment Team, Shropshire Council.

#### 2 ARCHAEOLOGICAL AND HISTORICAL BACKGROUND

**2.1** The Pitchyard pottery probably began working in the 18th century, and may have continued until at least 1833. In c. 1858 Edwin Southorn took over the business which by this time was producing clay pipes (Higgins, D, in Clark and Alfrey, 1987, p141). In the late 1870s the factory was rebuilt as the Raleigh Tobacco Pipeworks, said in 1885 to be one of the largest factories of its kind in England. In the 20th century, the pottery operated as the Salop Pottery Company and the Leigh Pottery. Production had ceased by the 1950s. A chimney and parts of the buildings were still identifiable in the late 1980s (Clark and Alfrey, 1987, p71).

## 3 THE WATCHING BRIEF

- **3.1** A watching brief on demolition work was carried out in December 2011. No groundworks were carried out during this work that disturbed the ground surface, and no below-ground archaeological deposits were therefore seen or recorded.
- **3.2** A photographic record of the exterior of the structures to be demolished was made prior to demolition.
- **3.3** The buildings were largely of brick construction of 18<sup>th</sup> and 19<sup>th</sup> century date with some 20<sup>th</sup> century modifications. Parts of the lower courses of the east wall on the street frontage were of limestone construction. These buildings will have been part of the 18<sup>th</sup> and 19<sup>th</sup> century pipeworks, and it is probable that the stonework in the east wall may have represented the remains of the earliest phases of the former industrial complex.

## **4 REFERENCES**

Clark, C and Alfrey, J, 1987: Benthall and Broseley Wood: Third Interim Report of the Nuffield Archaeological Survey, Ironbridge Institute

**Stamper**, **P A**, 1985: Benthall and Posenhall Parishes, Victoria County History of Shropshire

### **ABBREVIATIONS**


HER Historic Environment Record, Shropshire Council

NGR National Grid Reference

OS Ordnance Survey

SA Shropshire Archives, Castle Gates, Shrewsbury
TSAS Transactions of the Shropshire Archaeological Society

TSAHS Transactions of the Shropshire Archaeological and Historical Society





The Garage, The Mines, Benthall 2011

Figure 1: the location of the study area

## **Archaeology Service**

Shropshire Council Historic Environment Team, Environment Group, Shirehall, Abbey Foregate, Shrewsbury, SY2 6ND



Photo 1: The south end of the street frontage buildings, looking southwest



Photo 2: The east range of buildings on the street frontage, looking northwest



Photo 3: The site, looking south

# THE GARAGE, THE MINES, BENTHALL 2011



Photo 4: Doorway on the street frontage, with stone work to either side; (scales 2m and 1m)



Photo 5: The rear of the buildings on the street frontage, looking northeast



Photo 6: Demolition work in progress, looking southeast

# THE GARAGE, THE MINES, BENTHALL 2011