


DB 7/2/8

Cow Tag 106	Function Code S16-7 16-6	
Brief Description: [timber element, p/s, condition, fragments] TRUNCATED BLANK - FOX SCARF MISSING - cut modern to recover from pile AFT SCARF V. DAMAGED where cut back for 08 tingle.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD:- T.1 Lines 50 cm FOX OF AFT SCARF T.1 Lines around SEE T.N. from AFT END T.1 Lines AGE of 3rd T.N from FOX POSS. T.1 Lines AGE of 6th T.N from FOX FEATURE labels are in POSSIBLE correct locations, though pos. not outboard: T.3 Lines toward FOX end of tingle - centre plank lot of axe marks T.1 LINES BETWEEN 3rd + 4th T.N from FOX end local bearing conversions on board axe marks on board (see other side)		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial, Sapwood along lower edge 85H+15S at cut for 08 tingle. ARW = 2.2 mm 		
Recommended action: [samples, additional photos, moulding, queries and problems] - casting of axe marks under tingle (aft end, outboard) - outboard: photo of intentional marks under tingle > < + axe marks + general shot of tingle area. DOND.		
Cleaned: JS TJS 20/07/06 VT RG DV	Recorded: DV 25-07-06	Photos: ms 15/6/6
Checked: [corrections needed] NN. ✓	Initials & Date: NN 27/7/6.	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	

8/5/78
DBF 80

Inboard: Apart from type 1 lines, there are type 2 lines around the 6th keel nail and another possible type 2 line further along, which is grouped with the other type 2 lines.

Outboard: ~~next~~ next to 5th keel nail small type 2 lines (grouped)
Had fingle at aft end → nice deep axe marks with corner axe sometimes