

DB 19/2/8

Cow Tag <u>240</u>	Function Code <u>516.1</u>	
Brief Description: [timber element, p/s, condition, fragments] <u>Fragment, ^{forward} aft end sawn off probably in antiquity</u>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>Outboard: No notable features. Wood soft with hard concretions.</u> <u>Inboard: - Much deterioration of original surface on aft end.</u> - 4 ADD. NAILS AT AFT END OF INBD SCARF - POSSIBLE BORER DAMAGE ON INBD SCARF - 2 ELONGATED HOLES NEAR LAND AT AFT PART		
Wood Science: [rings, ARW, knots, sapwood, conversion] <u>Radial, fast grown. Saw patches of sapwood on the lower edge.</u> <u>c50H + 28. ARW = 185/52</u> <u>Grain beginning to 'run away' at aft end?</u>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: <u>VT</u> <u>27/07/06</u>	Recorded: <u>AK 28/7/6.</u>	Photos:
Checked: [corrections needed] <u>✓</u>		Initials & Date: <u>NN 28/7/6.</u>
Corrections Done [desktop, Faro Arm?]:		Initials & Date: