


DB 19/2/8

Cow Tag <i>246</i>	Function Code <i>519.1</i>	
Brief Description: [timber element, p/s, condition, fragments] <i>part of plank, very soft surface, both IB & OB.</i>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <i>NO noticeable features ???</i> <i>NOT VERY WELL CLEANED => CLEANED AGAIN!</i> <i>INBOARD: - VERY WORN + SOFT SURFACE</i> <i>- RATHER LONG + NARROW ADD. NAIL AFT OF 1 OF THE CLINKER NAILS, UPPER EDGE (FORW. PART OF PLANK, JUST ABOVE 2. TREENAIL FROM FORW. END)</i> <i>OUTBOARD: - INSCRIBED LINE TYPE 3 AT AFT END (POSSIBLY A 2. T) AT LOWER EDGE) x 2 of possibly modern?</i>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <i>Off axial at aft part.</i> <i>100% ARW = 2.05mm</i> <i>Rth beyond lower edge on growth band</i>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: <i>24/07/06</i> <i>LB, MS.</i>	Recorded: <i>25.07.06</i> AK	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: