


DB 19/2/8

Cow Tag 277		Function Code P2.9
Brief Description: [timber element, p/s, condition, fragments] SMALL FRAGMENT OF SCANT hull plank. Described as part of scant at Reel near stem.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos IN BOARD:- N.N.F OVERBOARD:- N.N.F → identified with ref to strike diagram as lower edge of P2.9 (upper part = 1047). Forward lower part of scant of P2.9		
Wood Science: [rings, ARW, knots, sapwood, conversion] 		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: 00/07/06	Recorded: 08/09/06	Photos:
Checked: [corrections needed] ✓	Initials & Date: NN 8/9/6	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	