



DB 11/3/8

| | | |
|--|--|---------|
| Cow Tag 396 | Function Code P & P A | |
| Brief Description: [timber element, p/s, condition, fragments] TRUNCATION ON AFT SCARF (INBOARD) OTHERWISE GOOD CONDITION | | |
| Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos INBOARD: - 'V' SHAPE MARKING, ON UPPER EDGE OF FOX END OF PLANK BETWEEN CENTRAL & UPPER TRUNNEL HOLES. INSCRIBED 'X' ADJACENT TO AFT END OF PLANK TO TRUNCATED TREE RING AT OUTBOARD: TOOLMARKS ON AFT SCARF 5 Double tree rings | | |
| Wood Science: [rings, ARW, knots, sapwood, conversion] 65 H. Radial at damaged aft scarf. ARW = 195 / 65 P.H. beyond lower edge on aft scarf. |  | |
| Recommended action: [samples, additional photos, moulding, queries and problems] photo: toolmarks on aft scarf OUTBOARD | | |
| Cleaned: VT BJ 26/04/06 | Recorded: 30/4/06 Demi Vancr | Photos: |
| Checked: [corrections needed] | Initials & Date: 25/5/6 | |
| Corrections Done [desktop, Faro Arm?]: | Initials & Date: | |



306 Pg. 8A Dent Vorse 27 April 2006

