



Cow Tag 623		Function Code P7.2
Brief Description: [timber element, p/s, condition, fragments] Intact plank, good condition, many nails (repair?)		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos Outboard: Outboard: tree nail with wedge hole in 1/2 centre of the plank. Inboard: included sapwood (healed scar?) forward of ^{aft} scarf. Approximately 20 cm forward of ^{inboard} aft scarf step-crescent shaped bevel with tool marks (axe)... related to scarf? Currently recorded as compression mark inboard.		
Wood Science: [rings, ARW, knots, sapwood, conversion] 75H + H/s. Pith beyond lower edge. Radial ARW = 173/75 Included sapwood (healed scar)!		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: VT 27/04/06	Recorded: 28.04.06 AK	Photos:
Checked: [corrections needed] ✓	Initials & Date: MM 14/6/6	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	



→ included sapwood.

623 P7_2 Angela Karsten 28 April 2006



! wedge of trench?