	01 11/2/30
Cow Tag 625	Function Code
Brief Description: [timber element, p/s, condition, fragments]	
Plank in fairly good condition, soft 018 face + distorted	
at aft edge by modern wedge driven into crack.	
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos	
iB: add. nail on scarf. forward end of plan	inscribed lines on a
018: wedge on one wooden fastener / trænail Poss. inscribed line close to 3rd treenail.	
	* V
a	
Wood Science: [rings, ARW, knots, sapwood, conversion]	
9. Julios Rolling P	the beneat
Shoppy sond alow.	so o
groups your abour.	
Recommended action: [samples, additional photos, moulding, queries and	
problems]	
8	
Cleaned: 25/05 Recorded: 31/05/0	Photos:
UB. MS. VT	
Checked: [corrections needed]	Initials & Date:
33.3.3.3.3.3.3.3.3.3.3.3.3.3.3.3.3.3.3.3	NN 21 6 L
	NN 21/6/6
Corrections Done [desktop, Faro Arm?]:	Initials & Date