

T.2

DB 21/2/8

Cow Tag 635	Function Code F49-0
--------------------	----------------------------

Brief Description: [timber element, p/s, condition, fragments]

Floor Striker - Sapwood


Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

For - axe marks
 - aft face - Tu
 - outboard: 5 nail holes on one joggle!

T.1	T.2	T.3	T.4 ✓	T.5	T.6	T.7	T.8
-----	-----	-----	-------	-----	-----	-----	-----

Wood Science: [rings, ARW, knots, sapwood, conversion]

Main stem = part aim, branch =
 starboard At timber hole.
 C + 60H + 12S + Be.
 (asymmetric pitch?)
 ARW = 110/72.



Recommended action: [samples, additional photos, moulding, queries and problems]

Photo as on point out - multiple nail holes, axe marks
 in chambered timber hole

Cleaned: 16/01/07	DV EC LOWIS, PAVE BS	Recorded: 1-2-07 DV	Photos: JV/sc 13/1/08
Checked: [corrections needed] XXX ✓		Initials & Date: NN 23/10/7	
Corrections Done [desktop, Faro Arm?]:		Initials & Date:	