

T2

DB 28/02/08

Cow Tag 639	Function Code # F3-0
-------------	-------------------------

Brief Description: [timber element, p/s, condition, fragments]  
 Fragment of ~~frame~~ Floor with a number of cracks.


Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

v. decayed.  
 lots of Sapwood - good for levels?  
 Hacked in ~~an~~ at part end  
 NB no indications of purple located at F58.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8


Wood Science: [rings, ARW, knots, sapwood, conversion]

C + c 40 H + 10 S  
 ARW = 16/50



Recommended action: [samples, additional photos, moulding, queries and problems]


Cleaned: 16/01/07 L.B	Recorded: 26/01/07 JS	Photos:
Checked: [corrections needed] —	Initials & Date: NN 2/11/7	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	



Forward

639 F3\_0 Ben R. Jennings 26 January 2007

Aft




639

25 CM

*hacked in anti-gravity*

Inboard



Outboard

