


DB 23/11/09

Cow Tag 669				Function Code FS7.1			
Brief Description: [timber element, p/s, condition, fragments]							
← TANK 11							
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING							
Remains of FS7.1, scarfed. lower section							
Half tree-wide hole on forward side							
T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
Wood Science: [rings, ARW, knots, sapwood, conversion]							
							
Recommended action: [samples, additional photos, moulding, queries and problems]							
Cleaned:			Recorded: 10/12/07 DV			Photos:	
Checked: [corrections needed]					Initials & Date:		
Corrections Done [desktop, Faro Arm?]:					Initials & Date:		