


DB 6/2/8

Cow Tag 093	Function Code TIMBER IB IB	
Brief Description: [timber element, p/s, condition, fragments] Inboard Timber - Number of cracks 12 on fore end / S12.5 18		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos DB - Axe work between T.N. holes IB - FRAMES impressions, & axe work. Inscribed line fore end. Clinker nails are drawn on the additional nail layer		
Wood Science: [rings, ARW, knots, sapwood, conversion] 100 H Radial. Pith beyond lower edge. ARW = 1.8 mm		
Recommended action: [samples, additional photos, moulding, queries and problems] Check / change layers of nails of S12.5. <u>Done</u>		
Cleaned: 22/08/06 SS	Recorded: VT 4/09/06	Photos:
Checked: [corrections needed] ✓		Initials & Date: NMIS/0/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date: