

APPENDIX 2:

SITE PHOTOGRAPHS



Appendix 2.1: View looking north along Main Street (site indicated)



Appendix 2.2: View looking south along Main Street (site indicated)



Appendix 2.3: View looking north-west along New Road (site indicated)



Appendix 2.4: Church of St Peter and St Paul, looking north-east



Appendix 2.5: View looking south from the churchyard of the Church of St Peter and St Paul



Appendix 2.6: View towards the site from Main Street looking south-east



Appendix 2.7: View towards the site from Main Street looking north-east



Appendix 2.8: East elevation of Building I



Appendix 2.9: South elevation of Building I



Appendix 2.10: East elevation of Building I, noting conservatory to left



Appendix 2.11: General view of GI in Building I, looking south-west



Appendix 2.12: General view of G5 in Building I, looking south, noting boxed in RSJs



Appendix 2.13: Detail of fire surround in G5, Building I, looking west



Appendix 2.14: Detail of cast iron fire back in G1, Building I, noting date of 1588



Appendix 2.15: General view of staircase in GI in Building I, looking north-west



Appendix 2.16: General view of F2 in Building I, looking south-east



Appendix 2.17: General view of F3 in Building I, looking south, noting shadow of blocked door (indicated)



Appendix 2.18: Detail of scroll and notch stop on chamfered beam in F3



Appendix 2.19: Detail of doorcase to door from G1 to G2



Appendix 2.20: General view of S2 looking south-east



Appendix 2.21: General view of S3 in Building 1, looking west



Appendix 2.22: General view of G6 in Building 2, looking south-west



Appendix 2.23: General view of F7 in Building 2, looking north



Appendix 2.24: General view of Buildings 2 and 3, looking east, noting modern garage in front



Appendix 2.25: General view of Buildings 2 and 3, looking east



Appendix 2.26: Detail of window in west elevation of Building 3, noting scar of blocked door below sill



Appendix 2.27: General view of G10 in Building 3, looking south-west



Appendix 2.28: General view of G12 in modern garages, looking west



Appendix 2.29: General view of Building 4, looking south-west



Appendix 2.30: Detail of southern end of east elevation of Building 2



Appendix 2.31: Detail of north elevation of Building 4



Appendix 2.32: Detail of east elevation of Building 4 from modern portal frame structure, noting blocked arched entrance (indicated)



Appendix 2.33: General view of interior of G14 in Building 4, looking south



Appendix 2.34: General view of interior of G15 in Building 4, looking east



Appendix 2.35: General view of interior of **F8** in Building 4, looking south



Appendix 2.36: Detail view of interior of **F8** in Building 4, looking southeast, noting timber lintel of former doorway



Appendix 2.37: Detail of king post truss in F8, Building 4



Appendix 2.38: General view of interior of F9 in Building 4, looking northwest

APPENDIX 3:

LISTED BUILDING DESCRIPTION

CHURCH FARMHOUSE

List entry Number: 1045500

Grade: II

LOCATION

Church Farmhouse, Main Street

County: Nottinghamshire

District: Newark and Sherwood

Parish: Oxton

DESCRIPTION

GV II Farmhouse. Late C17 and C19. Red brick, some ashlar. Plain tile roof. Single rendered central ridge stack. Ashlar coped gables with kneelers. Double depth plan. 2 storeys plus garret, 2 bays. Doorway with 6 fielded panel door and glazing bar overlight. 2 ashlar brackets support an ashlar hood. To the right is a single 2 light sash with single wooden mullion. Above are two 2 light glazing bar casements each with single mullion. Above first floor windows are 4 tie plates. The garden front has 2 tripartite casements. Above are two 2 light glazing bar casements all with wooden mullions. On the top floor are two C20 glazing bar casements. All windows have ashlar drip moulds.

Listing NGR: SK6298751317