



*Plate 1 St. Andrew's, Weaverthorpe, viewed from the south-east.*



*Plate 2 The northern pew area, partially completed, looking west.*





*Plate 3 The western end of the northern pews: limestone and chalk foundations, 19<sup>th</sup> century services, church foundations and underpinning, modern concrete beams and rubble, looking north-west.*



*Plate 4 The isolated limestone foundations (1012), with concrete(1005) to the left and 19<sup>th</sup> century brick services to the right, looking west.*





*Plate 5 Brick underpinning (1020) for church wall (1021) overlying compact chalky clays (1018), showing 19<sup>th</sup> century air duct (1015) to right and mid left. Viewed from the south.*



*Plate 6 The eastern end of the northern pews showing layers (1003), (1004) and (1002) underlying the black and blood-red floor tiles (1001), looking east. Note modern rubble (1013).*





*Plate 7 Collapse/depression (1025) within (1013), looking south-west.*



*Plate 8 The southern pews, following removal of the seating, viewed from the north-west.*





*Plate 9 ?Floor deposit (2013) in the central area of the southern pews, looking west.*



*Plate 10 Northern limestone foundations (2005), with later brick repairs (2004), underlying the nave flooring (2001) within the southern pews. Viewed from the south.*



*Plate 11 'Void' and deposit (2010) at the western end of the southern pews.*



*Plate 12 The likely 19<sup>th</sup> century brick structure (2007), with (2008) to the right, viewed from the east.*





*Plate 13 Remains of spoil (2011) leading to the disarticulated human remains (2014) in the western and central area of the south pews, looking east.*



*Plate 14 Detail of the arrangement of the disarticulated human remains (2014), viewed from the west.*



*Plate 15 Individual coffin lid within context (2014), looking south-west.*



*Plate 16 19<sup>th</sup> century floor (2001) and associated hardcore overlying 19<sup>th</sup> century brick foundations (2004), at the eastern end of the southern pews, viewed from the west.*



# Humber Field Archaeology

*Archaeological Consultants and Contractors*

The Old School, Northumberland Avenue,  
KINGSTON UPON HULL, HU2 0LN

Telephone (01482) 310600 Fax (01482) 310601

Email [hfa@hullcc.gov.uk](mailto:hfa@hullcc.gov.uk)

WEB. [www.hullcc.gov.uk](http://www.hullcc.gov.uk)



---

Project Management • Desk-based Assessment • Field Survey • Excavation Watching Briefs  
• Finds Research • Post-excavation Analysis • Inter-tidal Work

Humber Field Archaeology is an independently-funded part of the Humber Archaeology Partnership, a partnership serving The East Riding of Yorkshire Council and Kingston upon Hull City Council