


4 Cathedral Close RIPON

Site location map
showing the area
of the Scheduled
Monument (shaded)

4 Cathedral Close Ripon

Site Plan



4 Cathedral Close Ripon

Section






Fig. 4. The east facing section looking north, showing the edge of the masonry block, the fills of room 1 and the demolition layers beyond.



Fig 5. The masonry block during excavation



Figs 6 and 7. The masonry block under excavation, showing the crude walls of re-used brick and the cemented cobble/stone infill.





Fig 8. The south, interior side of Wall 1, showing the plaster with channeling, possibly for electric wiring.



Fig 9. East-facing section showing the fill in Room 1, and the thin layer of plaster on the south side of Wall 2.