



Fig. 10

11-13 Bargate: frontage






Fig. 11

11 Bargate: the rear






Fig. 12

11 Bargate: rear extension



THE BRIGANTIA ARCHAEOLOGICAL PRACTICE The Board Inn, Richmond

Fig. 13

11 Bargate: old fireplace in demolished section



Fig. 14

11 Bargate: old cupboards in rear extension






Fig. 15

11 Bargate: view south from extension to show curve of former stair turret





THE BRIGANTIA
ARCHAEOLOGICAL
PRACTICE

The Board Inn, Richmond

Fig. 16

11 Bargate: curve of former stair turret (arrowed)




Fig. 17

11 Bargate: the stairs.





Fig. 18



11 Bargate: original arch of upper corridor.




Fig. 19

13 Bargate: the rear.





Fig. 20

13 Bargate: rear view.





Fig. 21

13 Bargate: Victorian fireplace.





Fig. 22

13 Bargate: ground floor.





Fig. 23

The barn: frontage






Fig. 24



The barn: roofing materials at rear.





Fig. 25

The barn: blocked doors in frontage.





THE BRIGANTIA
ARCHAEOLOGICAL
PRACTICE

The Board Inn, Richmond

Fig. 26

The barn: bar-room, looking south.





Fig. 27

The barn: vaulted chamber.





Fig. 28

The stable.





Fig. 29

The stable: remains of hay-racks.





Fig. 30

The cottage.



Fig. 31

The cottage; brick chimney.

The Board Inn, Richmond







Fig. 32

The long range, looking south-west.





Fig. 33

Trough in yard.