



PLATE 21 STONE FOOTINGS AT NORTH END OF EASTERN ALCOVE



PLATE 22 DRESSED STONE IN NORTH EAST CORNER OF UNDERCROFT



PLATE 23 WALL FOOTINGS AND COBBLES NEAR SOUTH DOOR



PLATE 24 TT1 FROM THE NORTH - ?FLOOR SURFACES AND BURNT AREAS




PLATE 25 TT1 FROM THE NORTH – CHALK LINED SLOT AT BASE




PLATE 26
TT2 SHOWING PIT,
WALL FOOTINGS
AND CHALK
FLECKING FROM
WEST



PLATE 27 PACKED LIMESTONE FLOOR WITH STONES AND DISTURBANCES




PLATE 28 FLOOR SURFACES IN SOUTH WEST CORNER OF UNDERCROFT

PLATE 29
BASE OF P1
FROM THE NORTH




PLATE 30 BASE OF P2 FROM THE NORTH



PLATE 31 BASE OF P3 FROM THE SOUTH




PLATE 32
TOP OF WINDOW
IN WEST SIDE OF
UNDERCROFT
HALL




PLATE 33 TOP OF WINDOW IN WEST SIDE OF UNDERCROFT HALL



PLATE 34 TOP OF WINDOW IN SOUTH SIDE OF UNDERCROFT HALL



PLATE 35
ALTERED WINDOWS
ON WEST SIDE
OF UNDERCROFT

PLATE 36
EAST SIDE OF
SOUTH WINDOW,
UNDERCROFT
HALL



PLATE 37
WEST SIDE OF
SOUTH WINDOW,
UNDERCROFT
HALL



PLATE 38 REMAINS OF SECOND SOUTH WINDOW, UNDERCROFT HALL

PLATE 39
OPENING IN
SOUTH-EAST CORNER
UNDERCROFT HALL,
FROM OUTSIDE




PLATE 40 NORTH EAST CORNER OF SWIMMING POOL



PLATE 41 STABLE RANGE FROM THE SOUTH



PLATE 42 EASTERNMOST TRUSS IN STABLE BLOCK ROOF



PLATE 43 STABLE BLOCK ROOF – TRUSS WITH STRUTS



PLATE 44 STABLE BLOCK ROOF - RAFTERS