



PLATE 1 WELL HALL FROM THE WEST



PLATE 2 WELL HALL UNDERCROFT WING FROM THE EAST





PLATE 3 WELL HALL SOUTH WING FROM THE EAST



PLATE 4 UNDERCROFT FLOOR AT COMMENCEMENT OF WORK





PLATE 5  
TEST HOLE AT BASE  
OF WESTERN PILLAR,  
UNDERCROFT



PLATE 6 BRICK PATH, UNDERCROFT





PLATE 7 SLATE FEATURE AND RISE IN GROUND, UNDERCROFT



PLATE 8  
SLATE FEATURE  
EXCAVATED,  
UNDERCROFT





PLATE 9 WEST WINDOW BAY, UNDERCROFT



PLATE 10 ASHPIT FEATURE, UNDERCROFT





PLATE 11 LIME FLOOR, UNDERCROFT



PLATE 12 LIME FLOORS AND ASHPIT, UNDERCROFT





PLATE 13 BRICK AND DECAYED WOOD NEAR CENTRAL PILLAR



PLATE 14 LIME FLOOR NEAR SOUTH DOOR





PLATE 15  
ALTERED AND  
BLOCKED  
SOUTH DOORWAY



PLATE 16 UNDERCROFT FLOOR BENEATH RUBBLE FILL





PLATE 17  
BASE OF EASTERN  
COLUMN

PLATE 18  
EASTERN ALCOVE  
LOOKING NORTH





PLATE 19  
EASTERN ALCOVE  
LOOKING SOUTH



PLATE 20 DRESSED STONES AT NORTH END OF EASTERN ALCOVE - ?START OF  
STAIR





PLATE 21 STONE FOOTINGS AT NORTH END OF EASTERN ALCOVE



PLATE 22 DRESSED STONE IN NORTH EAST CORNER OF UNDERCROFT