



Plate 1. View of Nos. 40 & 42 Wheelgate. Street Frontage. Facing east.



Plate 2. View of Nos. 44 & 46 Wheelgate. Street Frontage. Facing east.



Plate 3. View of Nos. 42-46 Wheelgate. Rear of property. Facing west.



Plate 4. View of Nos. 44 & 46 Wheelgate. Rear of property. Facing east.



Plate 5. View of northern boundary to No. 46 Wheelgate. Facing north.



Plate 6. View of southern boundary to No. 42 Wheelgate. Facing south.



Plate 7. Post Hole Cuts 1011 and 1008 with wall 1002. Facing north west.



Plate 8. General view of Excavations Showing Stone Structure. Facing west.



Plate 9. Standing Stone Wall in Trench 3. Facing north.



Plate 10. View of Trench 1 Showing Well 1015. Facing east.



Plate 11. View of Trench 2 Showing Cuts 2008, 2010, 2012.  
Facing north.



Plate 12. View of Stone Structure within Elim Church  
Building. Facing north.

## APPENDIX 1

### Context Listing

<i>Context</i>	<i>Type</i>	<i>Munsel</i>	<i>Description</i>
<b>Trench 1</b>			
1001	Deposit	10YR 6/1	Mixed Limestone and Silty Clay
1002	Structure		Wall formed of irregular limestone blocks
1003	Structure		Surface of bricks
1004	Structure		Salt-glaze downpipe
1005	Deposit	10YR 5/6	Silty deposit beneath brick surface 1003
1006	Deposit	10YR 5/6	Silty deposit beneath downpipe 1004
1007	Deposit	10YR 5/6	Silty clay with stone packing -fill of post hole 1008
1008	Cut		Post hole - filled by 1007
1009	Deposit	10YR 4/2	Silty clay with limestone fragments
1010	Deposit	10YR 5/2	Silty clay - fill of post hole 1011
1011	Cut		Post hole - filled by 1010
1012	Deposit	10YR 4/6	Silty clay
1013	Deposit	2.5YR 3/3	Silty clay - fill of pit 1014
1014	Cut		Pit - filled by 1013
1015	Structure		Square limestone built Well
<b>Trench 2</b>			
2001	Structure		Brick wall footing
2002	Deposit		Brick packing and timber post - fill of post hole 2004
2003	Structure		Wall
2004	Cut		Post hole filled by 2002
2005	Deposit	10YR 6/4	Linear deposit of gravel and gritty limestone
2006	Deposit	10YR 5/3	Mixed sandy clay/sandy silt
2007	Deposit	10YR 4/2	Sandy clay - fill of pit 2008
2008	Cut		Pit filled by 2007
2009	Deposit	10YR 4/1	Silty sand - fill of post hole 2010
2010	Cut		Shallow sub circular post hole - filled by 2009
2011	Deposit	10YR 4/1	Sandy silt - fill of 2012
2012	Cut		Deep pit cut -filled by 2011
2013	Deposit	10YR 4/2	Mixed silty clay/grit and sand
<b>Trench 3</b>			
3001	Structure		Limestone wall continuous with 1002
3002	Structure		Probable floor surface formed of limestone blocks
3003	Deposit		Limestone rubble

## APPENDIX 2

### Drawing Archive Listing

<i>Drawing Number</i>	<i>Scale</i>	<i>Type</i>	<i>Description</i>
1	1:20	Plan	Pre-excavation plan Trench 1
2	1:20	Plan	Pre-excavation plan Trench 2
3	1:20	Plan	Post hole 1007 and deposits 1005/1006
4	1:20	Plan	Post hole cut 1008
5	1:20	Plan	Deposit 1009/1010
6	1:20	Plan	Wall 1002
7	1:10	Section	South facing section of Trench 1
8	1:10	Section	North facing section of Trench 1
9	1:10	Section	East facing section Trench 1
10	1:20	Plan	Plan of deposits 2007/2009/2011
11	1:20	Plan	Plan of cuts 2008/2010/2012
12	1:20	Plan	Plan of deposit 2013
13	1:10	Section	East facing section Trench 2
14	1:10	Section	South facing section of Trench 2
15	1:20	Plan	Plan of Trench 1 extension
16	1:10	Section	West facing section cut 2012
17	1:20	Plan	Plan of pit cut 1014
18	1:20	Plan	Trench 3 Outline and Wall 3002/3003



## APPENDIX 3

### Finds Catalogue

<i>Context</i>	<i>Type</i>	<i>Description</i>	<i>Weight</i>	<i>Spot date</i>
1007	Pottery	1 York glazed, 1 Beverley1 splashed, 2 Staxton/Potter Brompton, 1 Intrusive plant pot rim	33g	12th/13th Century
1009	Pottery	21 Staxton/Potter Brompton (1 base), 3 Beverley1, 1 York glazed, 2 Brandsby type, 2 medieval ?source	203g	13th/14th Century
1010	Pottery	2 York glazed, 1 Staxton/Potter Brompton	8g	12th/13th Century
1012	Pottery	2 York glazed	9g	12th/13th Century
2006	Pottery	5 Beverley1 splashed, 1 York glazed, 2 Beverley2	78g	13th/14th Century
2007	Pottery	2 Staxton/Potter Brompton, 5 Beverley1 (1 rim 1base), 1 York glazed ware	58g	12th/13th Century
2011	Pottery	5 Staxton/Potter Brompton, 10 Beverley1, 1 York glazed, 2 Beverley 2, 2 joining rim Beverley 1 cooking pot	203g	13th Century

## APPENDIX 4

### Photographic Archive Listing

#### Film 1: Colour Print

<i>Frame</i>	<i>Description</i>	<i>Scale</i>	<i>Facing</i>
1	ID Shot		
2	Trench 1 Pre-excitation	0.5m	South
3	Trench 1 Pre-excitation	0.5m	South
4	Trench 2 Pre-excitation	2x1m	South
5	Trench 2 Pre-excitation	2x1m	South
6	Post hole cut 1007	0.2m	North
7	Post hole cut 1007	0.2m	North
8	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
9	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
10	Wall 1002 and natural deposit	0.5m	East
11	Wall 1002 and natural deposit	0.5m	East
12	Trench 2 Pit cuts 2008/2010/2012	0.3/0.4/0.5m	North
13	Trench 2 Pit cuts 2008/2010/2012	0.3/0.4/0.5m	North
14	Trench 1 General shot post-exacavation	2m	West
15	Trench 1 General shot post-exacavation	2m	West
16	Trench 1 General shot showing Well 1015	2m	East
17	Trench 1 General shot showing Well 1015	2m	East
18	Trench 2 East Facing Section	2m	West
19	Trench 2 East Facing Section	2m	West
20	Trench 3 General shot showing Wall 3001 and surface 3002	0.5/0.3m	South east
21	Trench 3 General shot showing Wall 3001 and surface 3002		

#### Film 2: Colour Transparency

<i>Frame</i>	<i>Description</i>	<i>Scale</i>	<i>Facing</i>
1	ID Shot		
2	Trench 1 Pre-excitation	0.5m	South
3	Trench 1 Pre-excitation	0.5m	South
4	Trench 2 Pre-excitation	2x1m	South
5	Trench 2 Pre-excitation	2x1m	South
6	Post hole cut 1007	0.2m	North
7	Post hole cut 1007	0.2m	North
8	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
9	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
10	Wall 1002 and natural deposit	0.5m	East
11	Wall 1002 and natural deposit	0.5m	East
12	Trench 2 Pit cuts 2008/2010/2012	0.3/0.4/0.5m	North
13	Trench 2 Pit cuts 2008/2010/2012	0.3/0.4/0.5m	North
14	Trench 1 General shot post-exacavation	2m	West
15	Trench 1 General shot post-exacavation	2m	West
16	Trench 1 General shot showing Well 1015	2m	East
17	Trench 1 General shot showing Well 1015	2m	East
18	Trench 2 East Facing Section	2m	West
19	Trench 2 East Facing Section	2m	West
20	Trench 3 General shot showing Wall 3001 and surface 3002	0.5/0.3m	South east
21	Trench 3 General shot showing Wall 3001 and surface 3002		

#### Film 3: Black and White Print

<i>Frame</i>	<i>Description</i>	<i>Scale</i>	<i>Facing</i>
1	ID Shot		
2	Trench 1 Pre-excitation	0.5m	South
3	Trench 1 Pre-excitation	0.5m	South
4	Trench 2 Pre-excitation	2x1m	South
5	Trench 2 Pre-excitation	2x1m	South
6	Post hole cut 1007	0.2m	North
7	Post hole cut 1007	0.2m	North
8	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
9	Trench 1 Post hole cuts 1008 and 1011	0.3 and 0.4m	North west
10	Wall 1002 and natural deposit	0.5m	East