

Photo No.	Description	Date Taken	Taken By
001	Ground Floor former kitchen	22-06-2016	KKP
002	Ground Floor former kitchen	22-06-2016	KKP
003	Interior East Elevation	22-06-2016	KKP
004	Interior East Elevation	22-06-2016	KKP
005	Interior East Elevation	22-06-2016	KKP
006	Exposed Foundations	22-06-2016	KKP
007	Interior North Elevation	22-06-2016	KKP
008	Ceiling	22-06-2016	KKP
009	Interior East Elevation	22-06-2016	KKP
010	Interior West Elevation	22-06-2016	KKP
011	North Window	22-06-2016	KKP
012	Interior West Elevation	22-06-2016	KKP
013	Interior West Elevation Window	22-06-2016	KKP
014	Interior South Elevation	22-06-2016	KKP
015	Interior South Elevation	22-06-2016	KKP
016	Interior South Elevation	22-06-2016	KKP
017	Interior East Elevation	22-06-2016	KKP
018	Interior West Elevation	22-06-2016	KKP
019	Interior Chimney Breast, Ground Floor East Room	22-06-2016	KKP
020	Ground Floor East Room	22-06-2016	KKP
021	Ground Floor East Room	22-06-2016	KKP
022	Ground Floor East Room Window	22-06-2016	KKP
023	Interior West Elevation	22-06-2016	KKP
024	Interior South Elevation	22-06-2016	KKP
025	Interior East Elevation, Ground Floor	22-06-2016	KKP
026	Gallery Details	22-06-2016	KKP

Photo No.	Description	Date Taken	Taken By
027	Interior Doorway	22-06-2016	KKP
028	Interior South Elevation	22-06-2016	KKP
029	Gallery Details	22-06-2016	KKP
030	Gallery Details	22-06-2016	KKP
031	Interior South Elevation Ground Floor	22-06-2016	KKP
032	Interior Doorway	22-06-2016	KKP
033	Interior Doorway, Internal Doors	22-06-2016	KKP
034	General View from South	22-06-2016	KKP
035	Disused Staircase	22-06-2016	KKP
036	Main Staircase	22-06-2016	KKP
037	Area Under Main Stairs	22-06-2016	KKP
038	Interior Doorway into Hallway	22-06-2016	KKP
039	Main Staircase	22-06-2016	KKP
040	Main Staircase	22-06-2016	KKP
041	Main Staircase	22-06-2016	KKP
042	Main Staircase	22-06-2016	KKP
043	Exposed Stonework in Stairway	22-06-2016	KKP
044	First Floor Hallway	22-06-2016	KKP
045	Windows in First Floor Hallway	22-06-2016	KKP
046	Main Staircase	22-06-2016	KKP
047	Windows in Gallery Hallway	22-06-2016	KKP
048	Gallery Hallway	22-06-2016	KKP
049	Gallery Hallway	22-06-2016	KKP
050	View from Gallery Hallway	22-06-2016	KKP
051	Doorway above Gallery Entrance	22-06-2016	KKP
052	View from Gallery	22-06-2016	KKP

Photo No.	Description	Date Taken	Taken By
053	Gallery	22-06-2016	KKP
054	Gallery	22-06-2016	KKP
055	Ceiling from Gallery	22-06-2016	KKP
056	East Elevation from Gallery	22-06-2016	KKP
057	Ceiling from Gallery	22-06-2016	KKP
058	Internal South Elevation Windows from Gallery	22-06-2016	KKP
059	Gallery Hallway from Gallery	22-06-2016	KKP
060	Radiator in Gallery	22-06-2016	KKP
061	Radiator in Gallery	22-06-2016	KKP
062	North Elevation Window from Gallery	22-06-2016	KKP
063	Timber Corbels from Gallery	22-06-2016	KKP
064	Exterior North Elevation	22-06-2016	KKP
065	Doorway on North Elevation	22-06-2016	KKP
066	Ground Floor Windows on North Elevation	22-06-2016	KKP
067	First Floor Windows on North Elevation	22-06-2016	KKP
068	First Floor Windows on North Elevation	22-06-2016	KKP
069	Slit Windows on North Elevation	22-06-2016	KKP
070	North Elevation	22-06-2016	KKP
071	Exterior South Elevation	22-06-2016	KKP
072	Exterior South Elevation	22-06-2016	KKP
073	Exterior South Elevation	22-06-2016	KKP
074	Central South Elevation Detail	22-06-2016	KKP
075	Central South Elevation Detail	22-06-2016	KKP
076	Exterior South Elevation	22-06-2016	KKP
077	South Elevation Detail	22-06-2016	KKP
078	Exterior Doorway	22-06-2016	KKP

079	Exterior West Elevation	22-06-2016	KKP
080	Exterior West Elevation	22-06-2016	KKP
081	Exterior Doorways, South Elevation	22-06-2016	KKP
082	Carved foundation stones on South Elevation	22-06-2016	KKP
083	Courtyard on East side	22-06-2016	KKP
084	Courtyard on East side	22-06-2016	KKP
085	Courtyard on East side	22-06-2016	KKP
086	Carved foundation stones on South Elevation	22-06-2016	KKP
087	Carved foundation stones on South Elevation	22-06-2016	KKP
088	General View from SW	22-06-2016	KKP
089	General View from SE	22-06-2016	KKP